

## Kerbal Space Program - Bug #22710

### Docking with port attached to "Breaking ground" robotics cause NullPointerException

05/31/2019 06:23 PM - Jasper\_f

<b>Status:</b>	Resolved	<b>Start date:</b>	05/31/2019
<b>Severity:</b>	Low	<b>% Done:</b>	100%
<b>Assignee:</b>			
<b>Category:</b>	Gameplay		
<b>Target version:</b>	1.9.0		
<b>Version:</b>	1.7.1	<b>Language:</b>	English (US)
<b>Platform:</b>	Windows	<b>Mod Related:</b>	No
<b>Expansion:</b>	Breaking Ground, Core Game, Making History		

#### Description

##### What happens:

Docking crafts while ports are attached to the new "Breaking ground" robotics causes (1) crafts to become separated, with one flying off as if in 0G environment, or (2) cause in immediate explosion of said craft.

##### How to reproduce

- Create any rover-type vehicle with wheels (regardless of which)
- Attach to the craft: two G-01 Alligator hinges, one cubic octagonal strut, a G-00 hinge, and a docking port (any) in that order.
- Dock two vessels together using this "docking arm".

**Scenario #1:** docking two rovers to a test cargo module using the new "Breaking ground" robotics. Note that (re)docking a single craft appears to work.

<https://www.youtube.com/watch?v=nN1pgE1F7mU>

**Scenario #2:** docking the same rover (with wheels slightly tucked in) to Mk3 cargo bay.

<https://www.youtube.com/watch?v=bP-LR9Sscek>

##### Notes:

- Bug observed with stock install of KSP (KSP v1.7.1.2539).
- Happens with multiple command modules and wheels
- Regular docking without any robotic parts in-between appears to function normally so far

#### History

##### #1 - 06/01/2019 12:53 PM - Jasper\_f

- File [Bugreport] rover.craft added
- File [Bugreport - module].craft added

##### What happens:

Docking crafts while ports are attached to the new "Breaking ground" robotics causes (1) crafts to become separated, with one flying off as if in 0G environment, or (2) cause in immediate explosion of said craft.

##### How to reproduce

- Create any rover-type vehicle with wheels (regardless of which)
- Attach to the craft: two G-01 Alligator hinges, one cubic octagonal strut, a G-00 hinge, and a docking port (any) in that order.
- Dock two vessels together using this "docking arm".

**Scenario #1:** docking two rovers to a test cargo module using the new "Breaking ground" robotics. Note that (re)docking a single craft appears to work.

<https://www.youtube.com/watch?v=nN1pgE1F7mU>

**Scenario #2:** docking the same rover (with wheels slightly tucked in) to Mk3 cargo bay.

<https://www.youtube.com/watch?v=bP-LR9Sscek>

##### Notes:

- Bug observed with stock install of KSP (KSP v1.7.1.2539).
- Happens with multiple command modules and wheels
- Regular docking without any robotic parts in-between appears to function normally so far

Attached the two crafts used:

- [Bugreport] - rover
- [Bugreport] - module

**#2 - 06/01/2019 01:23 PM - Jasper\_f**

- File *screenshot7.png* added
- File *output\_log.txt* added

[Update #2:] Attached screenshot of console output and *output\_log.txt*. Not sure how to get a copy of the console output itself; hence the screenshot.

**#4 - 06/07/2019 11:57 PM - just\_jim**

- Status changed from *New* to *Confirmed*
- % Done changed from 0 to 10

**#5 - 06/12/2019 07:51 PM - chris.fulton**

- Status changed from *Confirmed* to *Ready to Test*
- Target version set to 1.7.2
- % Done changed from 10 to 80

Several Changes and bug fixes have been made, moving this bug to RTT and can you check it in 1.7.2.2555?

**#6 - 06/30/2019 02:16 AM - 18Watt**

- Status changed from *Ready to Test* to *Not Fixed*
- % Done changed from 80 to 50

I am still seeing this behavior in 2555. My attempts usually end with the partial destruction of one or both crafts.

When I observe this, it seems like the docking port force tries to invert one of the ports, so they end up facing the same direction. Most of my attempts have ended up with the ports facing the same direction, instead of facing the opposite direction and butted together. This makes the lighter craft rapidly spin with the docking port.

**#7 - 02/15/2020 05:48 PM - victorr**

- Status changed from *Not Fixed* to *Ready to Test*
- Target version changed from 1.7.2 to 1.9.0
- % Done changed from 50 to 80

We have made changes in this last release and would like your feedback please.

**#8 - 05/24/2020 10:28 PM - sschork**

- File *screenshot95.png* added
- File *screenshot99.png* added

Hi, being struck by this during career-mode play, I tried to break it down:

My versions are

Main 1.9.1.2788  
Making History 1.9.1  
Breaking Ground 1.4.1

- no addons of any kind
- linux

This works:

A rover without wheels docked to a fuel tank using a telescope arm (*screenshot95.png*).

It is possible to first undock, then redock using the arm.

The following results in violent bouncing and ultimately exploding of the vessel to the right:

Same as above, but with wheels on the rover (screenshot99.png).

I also tried:

- building both parts separately and then docking
- putting the docking ports on different heights, higher and lower; the bouncing starts whenever a wheel touches the ground
- giving the docking ports different orientations
- putting a fuel tank and/or a structural node between the telescope arm and the docking port
- giving the robotic arm more degrees of freedom by using multiple hinges and then de-motorizing them in unlocked mode shortly before docking
- the next larger type of docking ports
- using landing struts instead of wheels
- non-radial attachment of the first docking port
- different command modules, fuel tanks, etc.

EDIT this would have fitted better here: [#23177](#)

#### #9 - 08/13/2021 01:03 PM - Technicalfool

- *Status changed from Ready to Test to Resolved*

- *% Done changed from 80 to 100*

Should be resolved now. If it isn't, please continue to report.

#### Files

---

[Bugreport] rover.craft	55 KB	06/01/2019	Jasper_f
[Bugreport - module].craft	22.5 KB	06/01/2019	Jasper_f
screenshot7.png	1.8 MB	06/01/2019	Jasper_f
output_log.txt	882 KB	06/01/2019	Jasper_f
screenshot95.png	1.79 MB	05/24/2020	sschork
screenshot99.png	1.59 MB	05/24/2020	sschork