

Kerbal Space Program - Bug #24857

FTE-1 Drain valve can drain intake air

02/14/2020 05:30 PM - 050644zf

Status:	Closed	Start date:	02/15/2020
Severity:	Low	% Done:	100%
Assignee:			
Category:	Parts		
Target version:	1.9.1		
Version:	1.9.0	Language:	English (US), 简体中文 (Chinese Simplified)
Platform:	Windows	Mod Related:	No
Expansion:	Core Game		
Description			
FTE-1 Drain valve can drain intake air when attached to air intakes.			
Video showing how this bug work: (Chinese but enough to show how this bug work)			
https://b23.tv/av88826273			

History

#1 - 02/14/2020 06:37 PM - just_jim

- File Bottlerocket Rover.craft added
- File screenshot534.png added
- Status changed from New to Confirmed
- % Done changed from 0 to 10

Confirmed,

#2 - 02/14/2020 07:13 PM - just_jim

- File deleted (Bottlerocket Rover.craft)

#3 - 02/14/2020 07:14 PM - just_jim

- File deleted (screenshot534.png)

#5 - 02/15/2020 04:03 AM - Anth12

Fun bug ;)

#6 - 02/15/2020 11:48 AM - 050644zf

- File ResourcesGeneric.cfg added

Kerbal Space Program\GameData\Squad\Resources

```
RESOURCE_DEFINITION
{
    name = IntakeAir
    displayName = #autoLOC_501005 // #autoLOC_501005 = Intake Air
    abbreviation = #autoLOC_6002101 // #autoLOC_6002101 = Air
    density = 0.005
    unitCost = 0
    hsp = 10
    flowMode = ALL_VESSEL
    transfer = PUMP
    isTweakable = false
    isVisible = false
    iRESOURCE_DRAIN_DEFINITION
    {
        isDrainable = false
        showDrainFX = false
    }
}
```

```
}  
}
```

in line 134, there is a typo that add an 'i' before the 'RESOURCE_DRAIN_DEFINITION'

#7 - 02/16/2020 02:16 PM - gotmachine

Remark : it would have been a good choice to have
isDrainable = isVisible
as a default when no RESOURCE_DRAIN_DEFINITION is found
That would have prevented that issue, as well as the same issue on mods resources.

#8 - 02/19/2020 06:45 PM - just_jim

- Assignee set to just_jim

#9 - 02/28/2020 03:59 PM - victorr

- Status changed from Confirmed to Ready to Test
- Target version set to 1.9.1
- % Done changed from 10 to 80

We've made some changes in the latest build and would like some input on this issue please. Thanks.

#10 - 02/28/2020 04:00 PM - victorr

- Assignee deleted (just_jim)

#11 - 02/29/2020 05:49 AM - Anth12

- File 1.9.0 SPH.png added
- File 1.9.0 Runway.png added
- File 1.9.1 SPH.png added
- File 1.9.1 Runway.png added
- Status changed from Ready to Test to Resolved
- % Done changed from 80 to 100

I tested it as per the screenshots, tested it in flight
and I did some testing on multiple propellents and ore tanks.

No Air intake issues anymore (kind of liked this one ;))

Resolved

#12 - 03/13/2020 11:38 PM - chris.fulton

- Status changed from Resolved to Closed

Files

Screenshot_2020-02-15-01-21-46-560_tv.danmaku.bili.png	1.26 MB	02/14/2020	050644zf
ResourcesGeneric.cfg	4.16 KB	02/15/2020	050644zf
1.9.0 SPH.png	2.56 MB	02/29/2020	Anth12
1.9.0 Runway.png	2.46 MB	02/29/2020	Anth12
1.9.1 SPH.png	2.77 MB	02/29/2020	Anth12
1.9.1 Runway.png	2.64 MB	02/29/2020	Anth12